

## Case Study 2

Location: North England, Railway shunting yard

Problems:

1. Constant Engine movement for over 100 years has resulted in this yard being heavily contaminated with oil.

The hotspot near the track have been identified and over the last 10 years has had a 8 ADJ1000 pumps that are split into two zones.

Each Zone has: 1. x4 pumps

2. 1 container with compressor, multi-stage timer, Air dryer, Holding tank with level switch.

Results: Since the system has been installed and with bi monthly maintenance has recovered over 100,000 litres.

